HEADQUARTERS 7th Engineer Battalion (Rein), FMF FPO San Francisco 96602

3/TRB/cwb 5750 5 Jul 1968

IST

MAR

FINENGR BN

CMD CHRON

UNE 1966

De U

From: Commanding Officer To: Commanding General.

Ê

Commanding General, First Marine Division (Attn: Field Historian)

Subj: Command Chronology

Ref: (a) 120 5750.2 (b) FMFPac 5750.8 (c) Div0 5750.28

Encl: /(1) June Chronology

Nº Lat

(1) 注意。

 $\{ (z_i) \}$

162 3

化苯酰基乙基 法法法法 主的 无论在此状

Same Same Broke

1. In accordance with references (a), (b) and (c), enclosure (1) is hereby submitted.

DECLASSIFIED

BAISLEY By direction

1526 122 2



COMMAND CHRONOLOGY

1 June 1968 to 30 June 1968

INDEX

- PART I ORGANIZATIONAL DATA
- PART II NARRATIVE SUMMARY

PART III - SEQUENTIAL LISTING OF SIGNIFICANT EVENTS

PART IV - SUPPORTING DOCUMENTS

/TAB A - OFFICER ASSIGNMENTS

DECLASSIFIED

PART I

CRGANIZATION DATA

DESIGNATION 1.

LtCol R. FUNDERBURK

COMMANDER

5750 5 Jul 1968

7th	Engineer	Battalion	(Rein)),	FMF

(Data)

SUBORD INATE UNITS

HqCo	Capt. T.D. IEWIS	8 November 1968
ServCo	Capt. J.D. RIVERA	5 August 1968
ConVn	Capt. R.E. FRANZWA	28 August 1968
ConBu	Capt. M.J. ESPOSITO	4 February 1969
ConCu	lstlt G.H. REID	4 February 1969
C ouD II	Capt. M.G. LILLEY	7 July 1969
	ATTACHED UNITS	· .
lst Bridge Co	lstit D.A. PEASNELL	18 December 1968
3rd Bridge CO	lstLt D.L. STOMAN	17 December 1968

2. LCATION

7th Engineer Battalion	6 August 1965	DaNang, RVN
lst Bridge Co	8 December 1965	Da Nang, RVN
3rd Bridge Co	17 October 1966	Phu Bai, RVN

3. STAFF OFFICERS Executive Office

> S-1 ° s-2/3

> > s-4

21 September 1968 Major J.E. HANNAN CWO E.A. HUFNAGEL 1 January 1969 Capt. T.R. BAISLEY 18 October 1968 Maj. R.A. HUNTZINGER 18 August 1968 Enclosure (1) 1

. . . .

.

	Supp	ly Officer	4	lstLt A.S. BARBER	16	December 1968		
•	Sgt 1	aj		SgtMaj G.E. MOYER	26	September 1968	•	
4.	AVER/	GE MONTHLY	STRENG	en e	•			۰.
•	US	SMC	T. US	<u>SN</u>				
	OFF	ENL	OFT	ENL				
	55	1,310	2	24			, ¹	
5.	PERS	ONNEL GAINS	AND LOS	SES and Materia	· · ·			
		GAINS	•		LOS	SES	•	
	USMC		USI	۲ <u>ال</u> محمد مع ال	SMC	USN	· · ·	
OFF	3	an a	:	- Distance de la stradición	11	0		
ENL	21		22 A. () - 1.51.5.5.5.	62	0		
						н. н. И		• .
	2							•
			1354 C	3 			· • • •	
		na bahar		an a			*	
					•			م
			han an a					. •
		P = 0			1		- - : ! !	•
			1 1		•			
				•	· ·			. [.]
	¢.	a da tala su		Navazi a serie serie (da				
							.	
							۰.	
						· · ·		

6806

PART II

NARRATIVE SUMMARY

The 7th Engineer Battalion continued support of the III Marine Amphibious Force within the DaNang area. Platoons from the attached 1st and 3rd Bridge Companies are rendering additional support in the Chu Lai, Hue/Phu Bai, and Dong Ha area.

Company "A", 7th Engineer Battalion continues upgrading of Routes 33 and 30 for class 50 traffic. Work also continued on the Ha Thanh Dam with that project being approximately 37% complete at the end of the reporting period.

Company "B", 7th Engineer Battalion continued upgrading of Route 1 for class 50 traffic Completed construction of the Dien Ban Bridge at BT 057588.

Company "C", 7th Engineer Battalion continues upgrading of Route 5 north. for class 50 traffic.

Company "D", 7th Engineer Battalion continued upgrading of Route 5 south. On 9 Jun Company "D" started opening Route 5 south to An Hoa this road has been closed since the TET offensive and maximum effort will be made to open and upgrade this road for sustained military and civilian traffic. On 10 Jun 1968 Company "D" was relieved of the responsibility of the maintenance of Route 14 in support of Operation Mameluke Thrust and the 1st Engineer Battalion assumed this resposibility.

1st Bridge Company, 7th Engineer Battalion

Removed 45' M4T6 fixed span at BT 075559. Installed 5 float raft (88'4") at BT 064562. Removed 60' M4T6 fixed span at BT 055592. Installed M4T6 fixed span at (30') 2C 219554. Installed 91' M4T6 floating bridge at 2C 085008. Installed 30' M4T6 fixed span at 2C 209554. Installed 75' M4T6 fixed span at 2C 191559. Installed 21' M4T6 fixed span at 2C 188556. Installed 75' M4T6 fixed span at 2C 183556. Removed 38' M4T6 fixed span at 2C 188556. Removed 38' M4T6 fixed span at 2C 188556. Installed 120' M4T6 floating bridge at BT 005655. Installed 150' M-4 floating bridge at BT 041621.

3rd Bridge Company, 7th Engineer Battalion

Removed 135' M-6 floating bridge at YD 127668. Installed 60' M4T6 fixed span at YD 796283. Removed 156' M4T6 floating bridge at ZD 153010. Removed 135' M-6 floating bridge at YD 127668. Installed 100' M4T6 floating bridge at YD 085008. Installed 38' M4T6 floating bridge at YD 788273. Removed 165' M4T6 floating bridge at YD 912117.

Enclosure (1)

3

PART III

۰.

. 1

L. Topi	<u>Cs</u>	
a.	Personnel and Administration. None	
b,	Enemy, weather and Terrain	
TIME	INC IDENT	COORDINATES
011030H	Company "A" reports that grader hit mine. 2 USMC WIA.	BT 069693
020720H	Company "A" reports that M-54 detonated mine on Route 33. 1 USMC WIA, 1 USMC KIA.	AT 900806
061230H	Company "C" Doorts that Vietnamese child threw grenades into halted truck. Driver threw grenades out. 1 Vietnamese child WIA, taken to Hill 41 aid station.	ат 941645
121730H		AT 921579
141250H	Company "D" reports truck detonated large mine. 2 USID WIA (med-evac).	АТ 910486
141530H	Company "D" reports TD-15 detonated mine. Negative casualties.	AT 908506
171045H	Company "D" reports 14-51 detonated large mine. Extensive damage to vehicle - negative casualties.	AT 909485
171250H	Company "D" reports one USMC detonated large AP mine. 2 USMC WIA (med-evac).	AT 911508
17 1 435H	Company "D" reports M-51 detonated large mine. Extensive damage to M-51. 1 USMC WIA.	AT 908500
191358H	Company "D" reports finding one 8"X8" 20 1b box mine. Returned mine to CP.	ат 907498.
192120H	7th Engr Bn defensive perimeter received 2 incoming rounds of small arms fire. Negative casualties.	ат 945782
210915H	Company "B" reports M-51 struck ARVN who ran into street. 1 ARVN MIA. Accident report submitted.	BT, 027652
211055н	with electrical blasting cap. Removed and returned to Company "D" CP.	AT 907497 osure (1)
•		

211225 Н	Company "D" reports finding one 20 lb shaped charge with electrical blasting cap. Charge blown at road side.	AT	907498	
230905 H	Company "D" reports finding one 40 lb rock mine. Mine was burned in place.	AT	916525	
230915H	Company "D" reports finding one 40 lb rock mine. Mine was burned in place.	Δ T	915510)
242230H	lst Bridge Company reports that the Song Thu Bon ferry was blown by satchal charges placed by enemy swimmers. Ferry repaired.	ΆT	925533	
280800H	command detonated 155mm round med-evac called. Personnel at med-evac site received approximately 300 rounds small arms fire. Returned fire. Neg additional casualties.	BT	оц8606	
280845H	Company "D" reports USMC detonated M-26 while attempting to disarm booby trap, 1 USMC WIA (med-evac).	AŢ	91751)	
290708H	Company "B" reports finding M-79 round booby trap with neil as firing device. M-79 round was blown in place.	BT	034638	
300800H	Company "D" reports that sweep team received 30 rounds of small arms fire. Returned fire. Negative casualties.		92552 8	} ∙
301130H	Company "D" reports finding one chicom rocket rigget as booby trap. Rocket was blown in place.	AT	92651	? 21 - 12 - 12
3011 / ₄ 5H	Company "D" reports Vietnamese truck detonated one 10 lb mine. Negative casualties.			•
C.	Organization and Operations			n Like - A Hersen Hersen
-	(1) Officer Assignments - See TAB A, Enclosure (1)	÷		
a an	(2) Operations of the second of the second	-	•	,
	0 the second second by mapping ± 70 000 C ± 70			

2 June: Culverts and by-passes at ZC 209554, ZC 184556 and ZC 191559 on Route 14 are impassable. Company "D" sent a working party out to repair it, but were forced back due to the weather. High water flooded the Ha Thanh Dam site. Water was running around east side of the coffer dam and the river was rising 2" an hour. The last jump sill was being poured when the water started running into the working area. The pouring was halted about 6 inches from the top of the form. Progress will be delayed untill area can be cleaned up.

۲

ARVN engineers have not cleared right of way for installation of tactical wire near DaNang airfield. Water level continues to be too high to work at the Ha Thanh Dam project. Working area is under water with an eigh inch layer of silt on the jump sill. Transported 70 tons of concrete aggregate to the Ha Thanh Dam site. Began hauling material for Dien Ban bridge site (BT 055592).

4 June: High water has stopped progress at the Ha Thanh Dam site. Access road under water and evacuated equipment from dam site. Ha Thanh Dam project is 32% complete. Finished hauling 100 tons of 2 inch clean aggregrate to Ha Thanh dam project.

5 June: High water from recent rains continues to impede progress at the Ha Thanh Dam site. Coffer dam was reinforced and more work is required to bring the dam back to its original condition.

6 June: Helo lifted 7 loads of bridge and food supplies to lst Bridge personnel on Route 14 west. One load was dropped at AT 956655. Commencing 7 Jun 1968 work will be started on the An Hoa road. As previously stated this will require maximum effort thus requiring all men and equipment to diverted from ammo revetments to the opening of the road. SeeBee personnel in An Hoa have been informed of the above and have stated they will continue with the project. However, to insure timely completion, liaision at the III MAF Engr/1st Mar Div Engr level is recommended. Plan to commence opening in Hoa road from An Hoa north on 7 June 1968, Telcon with S-3 of 7th Marines on 061845 envisioned no security would be provided to commence engineer efforts for the north to south nor is security for working in this direction envisioned in the forseeable future.

7 June: This Battalion has taken 13 WIA's in support of Mameluke Thrust in connection with Route 14 west. Flood water damage at the Ha Thanh Dam has halted all progress. Much work will be required to bail the project out and again start productive work. Road from An Hoa north is open to AT 910485. Expect to have the road open to AT 906505 by 8 Jun 1968. 7th Marines are giving us one platoon of security.

8 June: Final word from 7th Marines was that security would be provided by 3/7 at 0800 9 June, to open the An Hoa road. The security arrived at 1015 on 9 June, causing a 24 hour delay.

9 June: Route 5 from An Hoa to Phu Loc-6 pioneered open.

10 June: Security has not been provided for the road sweep south from Phu Loc-6 to An Hoa. Work is progressing slowly from south to north. Major Hogan USA, Assistant I Corps Engineer advisor to ARVN stated that 7th Engr Bn will not have to complete the tactical wire installation near the DaNang Airfield. This decision was due to the fact that adequate ARVN personnel are now available to complete the project. Plan to assist 1st Engineer's with mine sweep from Thuong Duc to Hill 52 on Route 14 west.

11 June: 1st Div Engr will assume responsibility for upgrading Route 14 west from Hill 37 to Thuong Duc, in support of Operation Mameluke Thurst on or about 13 June 1968.

Enclosure (1)

6

12 June: The Song Cau Lau River Ferry was directed to be removed anytime after the morning of 13 June 1968, by Maj Miller Force Engineers Office III MF. The ferry will be removed on 14 June 1968 unless otherwise directed. 1st Div Engr requested this Battalion to effect repair to the Thoung Duc airfield. Liaison with Special Forces personnel at that position evidence that the above work is to be accomplished when the tactical units located at the air field are relocated. At this time only limited grading can/was accomplished by this Battalion. Any additional improvements will require the relocation of the units at the airfield. This decision must be made by higher headquarters. Due to the change in responsibility of the maintenance and upgrading of Route 14 west the 1st Engr Bn and removal of 7th Engr Battalion forces on or about 13 June from Thuong Duc it is recommented the 1st Engr Bn persue this project when the units at the airfield are relocated at an unknown later date.

III June: There have been 11 Marine casualties in three days on Route 5 (An Hoa) nine of these were security personnel and two were 7th Engr Bn personnel. A TD-15 and M-51 were also lost due to hitting mines on this road.

16 June: Continued adequate security for work on the An Hoa road is a problem. Ist Bridge Company personnel who proceeded to Thuong up were not able to repair bridge at 2C 186556. Will not be able to return to the bridge site until Wednesday. Security will not be provided till this time.

17 June: Company "A" continued to reinforce the earth dam and began cleaning the jump sill at the Ha Thanh Dam site. Company "D" opened the An Hoa road from check point #6 to An Hoa. A total of 35 personnel from Company "D", 7th Engr En were invloved.

18 June: Once again, no security was provided for mine sweep from Phu Loc-6 to An Hoa; however, there was security for the sweep from An Hoa north towards Phu Loc-6.

19 June: Because of intense enemy activity in the way of mines and snipers, the extent of work on Route 5 (An Hoa) was limited to filling craters, and two mine sweeps.

20 June: Coordination of infantry security for An Hoa road remains a problem. Also their tardiness in arriving at pre-desingated position. Daily mine sweeps of the An Hoa road coupled with security restrictions, that is work must stop by 1600 in order to return to respective combat bases, limits direct road maintenance/upgrading to approximately 4 hours daily. III MAF engineers (Maj Miller) requested that 7th Engr Bn provide one five float reinforced raft for use by 9th Engrs at Hill 63. 1st Bridge Co loaded raft for delivery to Hill 63. Laision made with 9th Engr Bn.

21 June: Two convoys passed over the An Hoa road today, road is in good condition. Ist Bridge Company delivered 5 float reinforced raft to Hill 63. Also worked on 120° fixed span at Dien Ban. 3rd Bridge Company completed preparations for helolift of 4 float reinforced raft to YD 69h301.

22 June: Company "D" accomplished the following work on the An Hoa road project: Route 5 graded from (AT 873468) to (AT 909480). 340 cu.yds. of fill hauled and spread at 40' bridge (AT 925608). 2 convoys passed over the An Hoa road today. Road in good condition.

23 June: Company "D" reports the following activity/progress on the An Hoa road: Hauled and spread 231 cu.yds. of crushed rock from (AT 909481) to (AT 909489). Rock was rough graded. Two convoys passed over the road during this reporting period.

24 June: The following is a summary of activity of the An Hoa road reported by Company "D": Emplaced 270 cu.yds. of 5" minus rock from (AT 904473) to (AT 906476). Emplaced 50 cu.yds. of 5" minus rock from (AT 907477) to (AT 908478). Road from (AT 908478) south is in good condition. One USHC convoy traveled to An Hoa and returned during this reporting period.

25 June: 1st Bridge Company reports that enemy swimmers with satchel charges totally destroyed three half pontoons at the Song Thu Bon ferry (AT 925533). Repairs took approximately 3/2 hours; it was operational at 251345H. On the morning of the 25th a Marine inadvertently ran into the mine field at ASP-1 site. He detonated an M-16 AP mine after running several yards into the mine field. Company "C", 7th Engr Bn despatched a team to remove the Marine from the mine field. Using a mine detector the personnel from Company "C" swept a path cut to the body and removed it from the mine field.

26 June: Company "D" accomplished the following progress on the An Hoa road: Hauled and spread 320 cu.yds. of rock between (AT 908479) and (AT 909485). Hauled and spread 4" of fill between (AT 904473) and (AT 906475) and finished grading. One Military/civilian convoy traveled to An Hoa and reurned during this reporting period.

27 June: 1st Bridge Company removed Dien Ban bridge except for transom assembly. Personnel received small arms fire and were advised by ROK forces to evacuate area due to artillery strike. Will remove transom 28 Jun 1968. The Dien Ban bridge was the last tactical bridge installed in the DaNang TACR. The only other tactical bridging installed are located on Route 14 west of Hill 52.

28 June: Company "D" accomplished the following on the An Hoa road project: Hauled and spread 630 cu.yds. of fill on Route 5 from (AT 908478) to (AT 909485), approximately 600 meters. 1st Bridge Company removed transom from Dien Ban bridge, now completely removed (100%). Also recovered Song Thu Bon ferry for possible installation of additional ferry.

29 June: Company "D" accomplished the following in the An Hoa road porject: Hauled and spread 435 cu.yds. of fill from (AT 893466) to (AT 896468) - approximately 300 meters. Hauled and spread 49 cu.yds. of fill from (AT 909483) to (AT 909484) - approximately 50 meters. This Bn received 276 sleaves of concertina, 3,000 - 100 meter bobbings of wire and 6,554 24" stakes for barrier project.

- 8

30 June: Company "D" reports the following information in conjunction with the An Hoa road: Hauled and graded 108 cu.yds. of fill between (AT 891465) and (AT 892466) - approximately 100 meters. Hauled and graded 169 cu.yds. of fill between (AT 909485) and (AT 910486) approximately 100 meters. This Battalion received 1,110 - 81; 2,220 - 51 and 363 - 32" steel pickets; 181,800 sandbags 140 pair of leather gloves and a total of 3,720 - 100 meter rolls of wire for DaNang Barrier project. Liaision, planning and organization was completed for the barrier project. Expect to start delivering supplies, men and equipment.

d. Plans

(1) Continue general support of all units within the 1st Marine Division TACR, or assigned by III MF Headquarters.

(2) Continue support of CAG units within 1st Marine Division TACR, or as assigned by III MAF Headquarters.

(3) Continue maintenance of Bridges within 1st Marine Division TACR, or as directed by III MAT Headquarters.

(4) Continue upgrading of Route 1.

(5) Continue upgrading of Route 13C.

(6) Continue upgrading of Route 33.

(7) Continue upgrading of Route 30.

(8) Continue upgrading of Route 5 to An Hoa.

(9) Continue construction of the Ha Thanh Dam.

(10) Continue construction of DaNang Wire Barrier.

n an farraight ann an an tair can canain gas an san stàir an t-tair an t-tair an t-tair an t-tair an t-tair an e. Training

· . .*

(1) Command indoctrination and information for newly arrived personnel and debriefing for those departing.

(2) 27 personnel attended the 1st Engineer Battalion "Land Mine Warfare School". (DaNang)

(3) 3 enlisted, 2 officers attended Embark School (Okinawa).

.

(4) 1 Marine attended Vietnamese Language School. (Okinawa)

(5) 1 officer, 1 SNCO, 1 enlisted Marine attended Division Leadership course.

(6) 1 Marine attended Embark School. (DaNang)

(7) 1 USN enlisted attended Disease Vector Control Course. (DaNang)

DECLASSIFIED

		(8) 8 Marines attended ID-15 Maintenance Course. (DaNang.)
		(9) 36 Marines attended MT Drivers course. (7th Engr Bn)
		(10) 1 Officer, 4 Enlisted attended ADM School. (Okinawa)
	(Japan)	(11) 2 Officers, 1 SNCO attended Nuclear Safety Officer course.
	f.	Logistics, Equipment and Supply
	* •	(1) Administration
	June	
	2	Received Truck M4U-18 Earth Auger to fill T/E deficiency.
	5	Command Material Readiness Inspection of the Battalion was conducted by 1st Marine Division.
	7	Command Material Readiness Inspection of 1st Bridge Company was conducted by 1st Marine Division.
	8	Airlifted culvert materials to An Hea with 2 M51A2's to open Route 5 north from An Hoi to Hill 37.
	10	Re-evaluated Engineer Equipment in 1st FSR and 3rd FSR and Red Balled remaining items that had become critical.
	11	Received two (2) TD-15 tractors to replace two (2) T/E deficiencies.
	12	Provided forklift support for 2/7 ISA.
та;	14	The three Force Engineer Battalions submitted the first consolidated T/E-T/O change under one cover to upgrade equipment and personnel of the Force Engineer Battalion.
	16	Conducted Command Material Inspection of "C" Company, 7th Engineer Battalion.
	17	Received Pile Driver Leads to fill T/E deficiency.
	21	Received 16 M422 1/4 ton trucks to fill T/E deficiency of M38A1 in lieu of M151's. Vehicles deadlined lack of seals and tools to perform acceptance checks.
	23	Conducted Command Material Inspection of "A" Company, 7th Engineer Battalion.
	25	Received one M543A2 wrecker and three M51A2 physical 68 rebuild program.
	27	Received TL-16 Scoop Loader to fill T/E deficiency.
	,	10 Enclosure (1)

4

DECLASSIFIED

Submitted requisition for barb wire and materials for Da Nang Barrier.

Hauled 160 ton of barb wire materials into 7th Engr Bn storage lot.
Continued to stock pile materials for the DaNang Barrier.

2.107.127

(2) Supply

28

7th Engineer Battalion FMF (AC 21300)

During the month of june the Battalion Supply Section processed ssl priority 02 and 360 priority 05 requisitions and 261 priority 12 and 17 requisitions. Also processed were 973 receipts from due, 942 issues from due and 31 issues from warehouse.

lst Bridge Company FMF (AC 21325)

During the month of June 1st Bridge Company Supply Section processed 232 requisitions. Also processed were 260 receipts from due, 197 issues from due and 35 issues from warehouse.

Motor Transport

Approximately 138,325 miles were logged on the Battalion's Motor Transport Vehicles during June.

the states a

Maintenance

The Battalion Maintenance Platoon completed 226 Motor Transport work orders during the month of June. A total of 235 work orders were submitted, 21 were sent to Maintenance Battalion. Total work orders for Engineer Equipment numbered 125 with 93 completed and 17 were sent to FSR.

Messing

The Battalion Mess Staff continued to provide four meals daily except on Sunday; the fourth meal being a midnight ration for night crews. On Sunday a brunch replaces breakfast and dinner.

Medical

The Battalion Aid Station treated 613 military and 20 Vietnamese. During the month of June the Dental Clinic treated 270 military and 15 Vietnamese.

g. Civil Affairs/Civic Action

(1) The Civic Action program continues on a daily basis.

(2) Activities were as follows:

(a) The MedCap program provided treatment for one hundred and ninety-one persons.

11

Enclosure (1)

(b) The Battalion sponsored, Vietnamese brickyard produced a total of 25,485 soil cement bricks during this period.

(c) A total of 50,987 soil cement bricks were issued for various civic action projects throughout Quang Nam Provice including the FLC children's hospital, and the construction of two schools in the DaNang area.

(d) Through the manufacture of concrete well rings in the Battalion sponsored brick factory, one deepwater well was constructed in the village of Hoa Thanh and one well was constructed for CAP Q-1. Further support in well construction was rendered III MAF Civic Action and 29th Civil Affairs Company in the distribution of well rings for use in their operational areas.

(e) Routine support was given small building projects through distribution of salvaged building materials.

(f) A five room school in the village of Hoa Thanh is 85% complete.

(g) A public meeting room is 15% complete in the village of Hoa Thanh.

PART IV

SUPPORTING DOCUMENTS

1. Officer Assignments, See TAB A of enclosure (1)

DECLASSIFIED

12

þ

	2				58/882	
	• •					
						•
		•	•			
	· .			•	1/EAH/obm	ана (с. 1916) 1917 — Прила Салана (с. 1917) 1917 — Прила (с. 1917)
					1 July	•
				·	· · ·	
	NAME	SERVIO	RANK	MOS	PRIMARY DUTY	
						1
	Headquarters Co			· · · ·		
		045512	LtCol	1302/0 302	BnCmdr	
	FUNDERBURK, RAY HANNAN, J. E.	049923	Maj	1302/0402	BnExecO	
	BAISLEY,T. R.	080663	Capt	1302	S-3	The service set our care of a
	HUFNACEL E. A.	079266	C/IO	0130	S-1/Adj/Iogal	and Barbart
	HULLZINGER R. A.	059050	Maj	1302	S-4	
	IVEY, B. D.	076764	CVO	1360/0210	Asst S-3	
	JOHNSON J. P.	0101180	1stIT	1302	Asst S-4	
	LEWIS T. D.	093253	Capt	2502	HqCoCmdr/CommO	
	PERKINS V. N.	097607	1stIT	1310	EngrEquipPltCmdr	
	ROCCO, C. A.	093399	Capt	1302	Asst S-3 Asst CivAffO	
	SCHMIDT P. T. SOWA, J. J.	097811 099389	1stLT WO	0130 1360	ConstPltCmdr	
	TURSE, E. J.	095349	1stIT	1302	CivAff0	
	WARDLAN C. M.	0100102	lstLT	1302	S=2	
			.,			a) Carrie Carrier Barrens .
	Service Company					
		000500	·	4 7 0		
Ν.	RIVERA J. D.	092528 096092	Capt	1302	ServCoOmdr	
	BARBER, J. S. LOPEZ A. A.	093261	jstLT Capt	3010/3502 1302	BnSupO ExclcO	т
	CARVER R. E.	093575	1stLT	1320/0430	UtilPltCmdr	
	DICKERSON C. R.	096541	1stLT		UtilPltCmdr	
	FEETY D. V. Jr.	098649	WO	1310	MeintPltOmdr	
	GOODE F. M.	0102777	2ndI/T	3502	EnMTO	
	"A" Company	•			· · · · ·	
	FRANZMA R. E.	083290	Capt	1302/0430/	5715 "A" CoCmdr	
	AOYAMA K. M.	0103117	2ndIT	1301	PltCmdr	•
	CRAM A. B.	0103164	2ndLT	1301	PltCmdr	
	HILLARD A. S.	094276	1stIC	1302	ExocC	and the second
	DOMMEY J.	096544	1stIT	1320/0430	PltCmdr	
	TIMERMAN J. H.	0103845	2ndLT	1301	PltCmdr	
	"B" Company	•	·			
		a secondaria de la				
	ESPOSITIO M. J.	093085	Capt	1302/1720	"B"CoOmdr	
	ECKENRODE D. J.	0102675	2ndL/T	1302	PltCmdr	
	LONG R. L.	0102094	1stIT	1302	PltCmdr	
	SOOK R.	0102847	2ndI/T	1302	PltCmdr	
	"C" Company					ANT A CHE ME LAND AND AND AND AND AND AND AND AND AND
	EEID G.H.	095009	4 	1700		·····
	GENTRAN J. A.	0102613	istLT 2ndLT	1302 1301	CoCmdr	
	KRUGER L. V.	0102065		1302	Pivondr Pltomdr	
	HULL R. T. III	094275	1stIT	1302	ExecO	
	MANGE C. B.	0100458	1stL [®]	1302	PltCmdr	X _
	DEMIKER J.E.	0100995	istLT	1302	PltCmdr	KDB-H

DECLASSIFIED