HEADQUARTERS 7th Engineer Battalion (Rein), FMF FPO San Francisco 96602

3/JJS/cwb 5750 9 Apr 1968

IST MARDIN

From: Commanding Officer

To: Commanding General, First Marine Division (Attn: Field Historian)

Subj: Commaand Chronology for period 1 March to 31 March 1968.

Ref: (a) 100 5750.2 (b) FMFPAC 5750.8 (c) Div0 5750.2B

Encl: V(1) March Chronology

1. In accordance with references (a), (b) and (c), enclosure (1) is hereby submitted.

R.E. FRANZWA By direction

TTH ENG BN

CMD CHRON

8961 NEUM

5750 9 Apr 1968

COMMAND CHRONLOLGY

1 March 1968 to 31 March 1968

INDEX

	VTAB A		Officer Assignments
PART	IV IV	1000 1000 1000 1000	SUPPORTING DOCUMENTS
PART	III	-	SEQUENTIAL LISTING OF SIGNIFICANT EVENTS
PART	II	· 	NARRATIVE SUMMARY
PART	I	, -	ORGAN IZATIONAL DATA

5750 9 Apr 1968

PART I

CRGANIZATION DATA

1. DESIGNATION

2.

3.

7th Engineer Battalion (Rein), FMF

C OMMANDER

LtCol. R. FUNDERBURK

	SUBORDINATE UNITS	
HqCo	Capt. T.D. LEWIS	7 November 1967
ServCo	Maj. R.A. HUNTZINGER	2 September 1967
ConVu	Capt. J.D. RIVERA	23 October 1967
ConBn	Capt. M.J. ESPOSITO	15 January 1968
Concn	Capt. J.D. BUCKELEW	28 May 1967
ColiDit	Capt A.A. LOPEZ	30 October 1967
· •	ATTACHED UNITS	
lst Bridge Co	Capt. C.A. ROCCO	2 November 1967
3rd Bridge Co	Capt. R.D. SMITH	4 November 1967
LOCATION		
7th Engineer Bn	6 August 1965	DaNang, RVN
lst Bridge Co	8 December 1965	DaNang, RVN
3rd Bridge Co	17 October 1966	DaNang, RVN
STAFF OFFICERS	•	-
Executive Office	Major J.E. HANNAN	2 September 1967
S-1	CHO E.A. HUFNAGEL	20 December 1967
s-2/3	Capt. R.E. FRANZWA	29 July 1967
S-4	Capt. T.R. BAISIEY	23 Sepember 1967

1

Enclosure (1)

Supply Officer	lstLt A.S. BARBER	12 November 1967
Sgt Naj	Sgt.Haj G.E. MOYER	4 September 1967
4. AVERAGE MONTHLY STRENGTH		

	MC	USN			
OFF	ENL	OFF	ENL		
50	1/181	2	24		

5. PERSONNEL GAINS AND LOSSES

्र की तेर उस

.

		GAINS	•• •		• • •	L	DSSES	
	USIC	•	USN	· •		USIC	USN	
O FF	4		0		OFF	1	0	
ENL	107		1	•	ENL	76	1	•.

30.00

÷

1

1. Filta el

С. м. ж. .

Enclosure (1) 🐭

- E

DECLASSIFIED

Nr.

PART II

NARRATIVE SUIMARY

The 7th Engineer Battalion Continued support of the III Marine Amphibious Force within the DaNang area. Platoons from the attached 1st and 3rd Bridge Companies are rendering additional support in the Chu Lai, Hue/Phu Bai, and Dong Ha areas.

Company "A", 7th Engineer Battalion continues upgrading of Routes 33 and 30 for class 50 traffic.

Company "B", 7th Engineer Battalion continued upgrading of Routes 1 and 12 for class 50 traffic.

Company "C", 7th Engineer Battalion continues upgrading of Route 5 north for class 50 traffic.

Company "D", 7th Engineer Battalion continued upgrading of Route 5 south for class 50 traffic..

1st Bridge Company, 7th Engineer Battalion

Repaired an 8¹^µ M4T6 fixed span at BT 055592. Installed a five float raft at BT 430109.

3rd Bridge Company, 7th Engineer Battalion

Installed a 231: MiT6 floating bridge at XD 735234. Retracted a 300: MiT6 floating bridge at XD 460400. Retracted a 120: MiT6 floating bridge at XD 298565. Retracted an 88:4" MiT6 ferry at XD 623303. Retracted an 88:4" MiT6 ferry at XD 755234. Retracted 105: MiT6 floating bridge at XD 781209. Installed a 150: MiT6 class 35 floating bridge at XD 913117.

Service Company, 7th Engineer Battalion provided 2,138,000 gallons of water from their nine (9) water points for use in the DaNang TACR.

PART III

1. Topics

a. Personnel and Administration. None

b. Enemy, weather and Terrain

TIME INCIDENT

Oll151H D/7 reported that M-51 from Service Co., 7th Engr AT 9 hit 40 lb mine, possibly command detonated. M-51 severly damaged, 2 USMC WIA, Med-evac.

AT 923528

COORD INATES

6803

Enclosure (1)

021010H	D/7 mine sweep found one 40 lb box mine, pressure type. Blown in place.	AT 923528
040845н	A/7 mine sweep found one MIAl anti-tank mine. Removed and blown off road.	AT 899809
OL13.30H	D/7 sweep team found one 20 lb satchel charge in middle of road. Contained schrapnel and was designed for air burst. Removed and blown.	AT 931524
07092 0 H	D/7 sweep team received small arms fire from approx 15-20 VC. Returned 200 rds. small arms and 10 rds $81\rm{mm}_{\odot}$	AT 923528
10 1107H	B/7 sweep team received 5 or 6 sniper rds. Took cover. Did not return fire.	BT 040653
1 40855н	B/7 reported bridge blown. Reported to S-3 7th Engr Bn.	BT 0 76 559
11,1630 H	D/7 reported M-52 with lowbed hit mine. Received small arms fire. Truck returned to Company "D" CP, 3 USMC WIA Med-Evac.	AT 960584
2015œh	B/7 sweep team received approx 100 rds small arms, plus 10 rds mortar fire. 2 USMC WIA (minor).	AT 978623
301000H	B/7 reported M-51 hit mine. 2 front tires blown out. Négative WIA.	AT 985637
C.	Organization and Operations	
	(1) Officer Assignments - See TAB A, Enclosure (1)	
	(2) Operations	
Phu Loc.	1 March: Spread 175 cu.yds. of rock on Route 5 Crushed 25 cu.yds. of rock. Replaced bridge on Rout	south of e 33 with (3)

Phu Loc, Crushed 25 cu.yds. of rock. Replaced bridge on Route 33 with (3) 32 %48" culverts. Completed 6 culvert bunkers 8X8X8 at Cap E-4. Completed repairs of bridge on Route 1 at 018675.

2 March: Completed (1) one 4X10 head at CAG-2, completed (2) two Ammo Bunkers at CAP S-3. Have completed destroying 27 VC caves and bunkers, two French bunkers and one house with demolitions. Spread 90 cu.yds. of rock below Fhu Loc on Route 5 south, crushed 30 cu.yds. of rock at An Hoa. Placed 190 cu.yds. of rock on Route 33.

3 March: Destroyed 4 damaged bunkers at CAP S-3, completed bunkers at CAP E-4.

4 March: Found triple culvert at AT 943670 blown, used 65 cu.yds. of fill and 15 cu.yds. of rock for repairs. Constructed bypass. Placed 130 cu.yds. of rock on Route 5 below Fhu Loc.

4

Enclosure (1)

5 March: Spread 80 cu.yds. of fines and graded Route 33. Destroyed one house and 3 bunkers at CAP D-7. Located one box mine at AT 941641, mine detonated whild being grappled out crater was filled. Spread 95 cu.yds. of rock on Route 5 south of Phu Loc. Hauled. spread and compacted 1,180 cu.yds. of fill at Ammunition Storage area at the DaNang Airbase.

6 March: Filled one 8'X4' crater at 062655. CAP S-4 completed (1) one ammo bunker and 4 intermediate bunkers on berm line. Spread 1,000 gallons of asphalt on Route 5, Hill 37 and Maintenance area. Hauled, spread and compacted 1,478 cu.yds. of fill at Ammunition Storage area at the DaNang Airbase.

7 March: Completed bridge repair at 076559. Unloaded 3 cu.yds. of fill on sandbag culvert at 068563. Upgraded and placed 735 cu.yds. of fill on Anderson Trail west. 900 gals asphalt distributed on Route 12 east, 145 cu.yds. of fines spread and graded on Route 33. Poured footings for headwalls on Route 33. Emplaced 1,380 cu.yds. of fill to berm job DaNang Airbase.

8 March: Spread 115 cu.yds. of fines and 340 yards of fill on Route 33. Spillways for triple 48" culverts on Route 33 complete. 120 cu.yds. of fill hauled to eroded section on Route 5. CAP S-3 4 culvert bunkers complete. 780 cu.yds. of fill spread on Anderson Trail. Emplaced 1,390 cu.yds. of fill to berm job at DaNang Airbase.

9 March: CAG-2 living quarters and 4 culvert bunkers completed. 966 cu.yds. of fill spread on Anderson Trail west. 340 cu.yds. of fill hauled to eroded section of Route 5. Spread 130 cu.yds. of fill on Route 33. Emplaced 1,875 cu.yds. of fill at berm job at DaNang Airbase.

10 March: Completed one (1) 16X32 tin roof strong back at CAP B-1.

ll March: Repaired decking on bridge at AT 943691 Route 5 south. Spread 150 cu.yds. of fill on eroded section of Route 5. Spread 265 cu.yds. of fill and 115 cu.yds. of fines on Route 33. Emplaced 3,191 cu.yds. of fill at berm job at the DaNang Airbase.

12 March: Completed bridge on Route 6 at AT 957717. 6X10 4 hole head complete at Oldfield. Anderson Trail west hauled and spread 990 cu.yds. of fill. Spread 60 cu.yds. of fill and 40 cu.yds. of rock on Route 33. Replaced bridge on Route 33 at AT 928794 with (2) 36" culverts. Emplaced 3,060 cu.yds. of fill at berm job at DaNang Airbase.

13 March: Finished one (1) culvert bunker at CAP S-1. Hauled and spread 206 cu.yds. of fill on Anderson Trail west. Placed 15 cu.yds. of fill on bridge apporach on Route 6 at AT 957717. Completed work at CAP B-4. Spread 48 cu.yds. of rock and 168 cu.yds. of fill on Route 33. Emplaced 4,020 cu.yds. of fill at Airfield berm job.

Enclosure (1)

5

14 March: Spread 130 ca.yds. of fines and 225 ca.yds. of fill on Route 33. Hauled and spread 975 cu.yds. of fill on Anderson Trail. Completed culvert bunker at CAP D-1. Emplaced 1,360 cu.yds. of fill at berm job at the DaNang Airbase.

15 March: Hauled and spread 40 cu.yds. of rock and fill to tank bypass on Houte 18. Hauled and spread 1,050 cu.yds. of fill on Anderson Trail west. Spread 155 cu.yds. of fines and 250 cu.yds. of fill on Route 33. Emplaced 1,258 cu.yds. of fill at berm job at the DaNang Airbase.

16 March: Hauled and spread 500 cu.yds. of fill on Anderson Trail. Put 10' extension on 18" culvert on Route 18. 105 cu.yds. of fill hauled and spread on Anderson Trail west. Emplaced 2,828 cu.yds. of fill at berm job at the DaNang Airbase.

18 March: Graded Route 5 from AT 945707 to AT 918728. Spread 150 cu.yds. of fines and 150 cu.yds. of fill on Route 33. Replaced bridge on Route 33 at 908792 with 2-36" culverts. Completed 16X32 strongback and one (1) 6X10 4 holer, at CAG-2. Hauled and spread 600 culves, of fill at the Ha Dong Bridge approach. Spread and graded 378 culves, of fill at tank by-pass on Route 1B. Checked all bridges on Route 1 from the ferry to the Song Thu Bon Bridge. Emplaced 3.106 cu.yds. of fill at berm job at the DaNang Airbase.

19 March: Spread 250 cu.yds. of fines and 260 cu.yds. of fill on Route 33. Completed one (1) culvert bunker, one (1) 8X8 bunker at CAP S-1. Dug 120' of trench line at 7th Comm Bn CP area. Hauled and spread 335 cu.yds. of fill at tank by-pass. Repaired ramp on bridge at Song Thanh Quit. Emplaced 2,287 cu.yds. of fill at berm job at the DaNang Airbase.

and the second 20 March: Began clearing area for 60" culvert at Route 5 north at 946707. Assembled 36' of 60" culvert and 36' of 48" culvert. Hauled and spread 450 cu.yds. of fill at the tank by-pass. Spread 100 cu.yds. of fines and 200 cu.yds. of fill on Route 33. Repaired M4T6 pontoon at Song Cau Do. Emplaced 1,040 cu.yds. of fill at berm job at the DaNang Airbase event is the set of the train of the set of the set of the set 2 (2 a c)

21 March: Removed bridge at AT 946707 on Route 5. Completed one (1) culvert bunker at CAP S-1. Spread 250 cu.yds. of fill on Route 33. Checked ferry at Song Thu Bon. Emplaced 2,114 cu.yds. of fill at berm job at the DaNang Airbase satures of the second for the factor of a factor of 化合物 的复数缝 的复数形

22 March: Completed replacing bridge on Route 5 north at AT 946707. Emplaced 160 cu.yds. of fill at bridge site AT 946707. Installed five float raft class 60 at BT 430109. Repaired pontoons on bridge at Song Cau Do. Completed (1) 16X36 strongback. Hauled and graded 366 cu.yds. of fill in preparation for helo pad at 3/27 CP. Hauled and spread 155 cu.yds. of fill on Route 33. Emplaced 2,579 cu.yds. of fill at berm job at the Dallang Airbase. Return the state of the sta

The second second second

n 19 dhean a' shekara da 1960 karayetay, sehini dava silasi gini ilayyati s an Greensam on the Carlos Subram and Strand and Arthur Arthur and Arthur and Arthur and Arthur and Arthur and A 1986 - Arthur Arthur and Arthur and Arthur Green Arthur and Arthur and Arthur and Arthur and Arthur and Arthur a the second s

DECLASSIFIED

.

<u>i en la completa</u>

23 March: Spread 6,000 gallons of oil on Route 5 south. Hauled, spread and graded 336 cu.yds. of fill on the tank by-pass. Loaded one (1) M-6 bridge on trailers at FLC for delivery to ferry pier at III MAF. Emplaced 2,723 cu.yds. of fill at berm job at the DaNang Airbase.

25 March: Graded Route 5 north from AT 946707 to AT 912743. Checked all bridging on Route 1 from Song Cau Do to the Song Cau Lau. Hauled 105 cu.yds. of sand from 3rd 8" How Btry. Hauled and spread 666 cu.yds. of fill to tank by-pass on Route 1B. Emplaced 2,000 cu.yds. of fill at berm job at the DaNang Airbase.

26 March: Spread 6,000 gallons of oil on Route 5 from AT 911743 to AT 925607. Hauled and spread 936 cu.yds. of fill at the tank by-pass on Route 1B. Completed (8) eight strongbacks at 2/27 CP area. Hauled 138 cu.yds. of sand for the CAP Units. Hauled 135 cu.yds. of fill to 3rd 8" How Btry. Emplaced 3,791 cu.yds. of fill at berm job at the DaNang Airbase.

27 March: Spread 6,000 gallons of bunker oil on Route 5 south between AT 945706 and AT 942662. Checked all bridges on Route 1 from the Song Cau Do to the Song Cau Lau. Assisted CAP Units by hauling 60 cu.yds. of sand. Emplaced 1,850 cu.yds. of fill at berm job at the DaNang Airbase.

28 March: Checked all bridges on Route 1 from the Song Cau Bo to the Song Cau Lau. Hauled and spread 100 cu.yds. of fill on Route 33. Repaired bridge on Route 4. Removed bridge at AT 960706 in preparation for installation of two culverts. Replaced decking on bridge at AT 962716. Hauled and spread 900 cu.yds. of fill and 6,000 gallons of bunker oil on Route 12 east. Spread 5,500 gallons of bunker oil on Anderson Trail west. Completed (6) six 16X32 strongbacks at the 2/27 CP area: Emplaced 1,960 cu.yds. of fill at berm job at the DaWang Airbase.

29 March: Checked all bridges from the Song Cau Do to the Song Cau Lau. Hauled 115 cu.yds. of fill to the gun pads at 8" How Btry. Hauled and graded 1,182 cu.yds. of fill on Route 12 east. Completed repairs to bridge on Route 6 at AT 962716. Replaced bridge at AT 960706 with 2 48" culverts. Emplaced 2,000 cu.yds. of fill at berm job at the DaNang Airbase.

30 March: Hauled 170 cu.yds. of fill to road between Hill 37 and ferry site. Hauled and graded 816 cu.yds. of fill on Route 12 east. Spread 1,000 gallons of bunker oil on tank by-pass Route 1B. Completed 2 strongbacks at 2/27 CP area. Hauled and spread 200 cu.yds. of fill on Route 33. Emplaced 2,000 cu.yds. of fill at berm job at the DaNang Airbase.

DECLASSIFIED

Sec. Sec. 4

Enclosure (1)

1.1.1.1.1

later genti

d. <u>Plans</u>

(1) Continue general support of all units within the 1st Marine Division TACE, or as assigned by INI MAF Headquarters.

(2) Continue support of CAG units within 1st Marine Division TACR, or as assigned by III MAF Headquarters.

(3) Continue matintenance of Bridges within 1st Marine Division TACR, or as directed by III MAF Headquarters.

(4) Continue upgrading of Route 1.

(5) Continue upgrading of Route 13C.

(6) Continue upgrading of Route 33.

- (7) Continue upgrading of Route 30.
- (8) Continue upgrading of Route 5.
- (9) Continue upgrading of Route 12.
- e, Training

(1) Command indoctrination and information for newly arrived personnel and debriefing for those departing.

(2) 34 personnel attended the 1st Engineer Battalion "Land Mine Warfare School". (DaNang)

 $q_{\rm e}$ (1) , can brief purph of the explored with 14 and 18 within 145 large 10^{-1}

(3) 1 Marine attended Comm/Crypto School. (Japan)

(4) 1 Officer and 1 Enlisted attended Embark School. (Ckinawa)

external control of the second s

(5) 1 Marine attended Scuba School. (Philippines)

((7) 1 Officer and 4 Enlisted attended ADM School. (Ckinawa)

((8) 1 SNCO and 1 NCO attended Division Leadership Course.

(9) 2 Marines attended Basic Organic Supply Accounting Course

given at FLC.

- Pro againg

- - (I). Breakishe eigeneiter til lette Fr.

(A) Constance House 2 start relation in

(p) Calification oppositions of theory bile

Enclosure (1)

kyveise vie a mis masse inte i tam more nemer hermonie (1, i sprime or welle inte securi velationel a tam in souch

8

- 1917 - Marya na ganzik katalogiki katika disi ang katalogiki di katalogiki Malikula (katalogiki)

- f. Logistics, Equipment and Supply
 - (1) Adiminstration

March

- 1 Submitted request to CG III MAF for 7 P153 mine detectors in accordance with CG III MAF msg 280054Z February 1968.
- 2 Submitted request to CG III MAF for a special allowance of 8 TD-18 tractors.
- 6 Provided 150' of MAT6 floating bridge to 3rd Bridge for use in Northern ICTZ. This bridge is one of eight US Army bridges previously received.
- 7 Provided 65' M-6 bridging to RMK for installation at Son Cau Do River Bridge.
- 9 Provided 150' M:T6 bridging to 3rd Bridge. This is part of eight US Army sets provided for ICTZ requirements.
- 10 Conducted Command Material inspection of "B" Company, 7th Engr. Bn.
- 11 Received one 105 air compressor to fill T/E deficiency.
- 14 Provided 140' of Mart6 Army bridging to 3rd Bridge Company at Phu Bai. Delivered D-6 tractor and 7's yard scraper to POE for embarkation to the 11th Engineer Battalion. Delivered 140' of M4T6 floating bridge (Army) to POE. Received one M38A1 jeep; T/E deficiency remains at 14.
- 15 Received 4 chain saws, McCulloch Model 795, from Force Engineer for test and evaluation.
- 16 Elements of the lith Engineer Bn. arrived. Provided billeting and messing facilities for two days. Provided 2 men/10 bridge trailers to FIC to identify and relocate M-6 bridging.
- 17 Held Command Material Maintenance inspection of "C" Company, 7th Engr Bn.
- 18 Remaining elements of 45th Engineer Group arrived at CP. Delivered 2 Rotary Tillers to POE for TAD with 14th Engineer Battalion USA for period of 30 Days.
- 20 Received one 5 KM Floodlight Unit to fill T/E deficiency.
- 21 Elements of the 14th Engineer Bn (USA) departed this CP. The remaining elements of the 45th Engineer Group (USA) arrived at this CP the movement of this unit is now complete. Received one M38Al rebuilt jeep.

9

.

Enclosure (1)

- 23 Received one M52A2 tractor from FLC.
- 25 Conducted Material Management inspection of "D" Company, 7th Engr Bn. Provided men and equipment to load M-6 bridging at FLC for delivery to POE.
- 28 14 Bridge trailers were dispatched to northern ICT2. These trailers have organic bridging of 3rd Bridge Company aboard.
 - (2) Supply

7th Engineer Battalion FMF (AC 21300)

During the month of March the Battalion Supply Section processed 367 priority 02 and 736 priority 05 requisitions and 484 priority 12 and 17 requisitions. Also processed were 742 receipts from due, 684 issues from due and 244 issues from warehouse.

1st Bridge Company FMF (AC 21325)

During the month of March 1st Bridge Sup ly Section processed 135 requisitions. Also processed were 113 receipts from due, 86 issues from due and 27 issues from warehouse.

3rd Bridge Company (AC 21335)

During the month of March 3rd Bridge Supply Section processed 211 requisitions. Also processed were 62 receipts from due, 29 issues from due, and 115 issues from warehouse.

Motor Transport

Maintenance

Approximately 114,727 miles were logged on the Battalion's Motor Transport Vehicles during March.

The Battalion Maintenance Platoon completed 51 Motor Transport work orders during the month of March. A total of 31 work orders were submitted, 12 were sent to Maintenance Battalion. Total work orders for Engineer Equipment number 113 and 92 completed and 18 were sent to FSR.

The Battalion Mess Staff continued to provide four meals daily except on Sunday; the fourth meal being a midnight ration for night crews. On Sunday a brunch replaces breakfast and dinner. unch reputtes of the second second

Medical states

Sector Sector Sec

The Battalion Aid Station treated 651 Military and 20 Vietnamese. During the month of March the Dental Clinic treated 299 Military and 18 Victnamese.

Enclosure (1)

化二氟乙酸 的复数法国际公司

a the second second

And the set of the set of the

DECLASSIFIED

10.40

g. Civil Affairs/Civic Action

(1) The civic action program continues on a daily basis.

(2) Activities were as follows:

(a) The MED CAP program provided treatment to two hundred fifty three (253) persons.

(b) The battalion sponsored, Vietnamese brickyard produced a total of twenty six thousand four hundred thirty one (26,431) soil bricks.

(c) A total of twenty one thousand eight hundred thirteen (21,813) bricks were released from the 7th Engineer Battalion Brick Factory during the month of March for various projects.

(d) Seven (7) scholarships ere given to Vietnamese children who showed good academic ability.

PART IV

SUPPORTING DOCUMENTS

 $\sqrt{1}$. Officer Assignments, See TAB A of Enclosure (1)

Enclosure (1)

DECLASSIFIED

;

DESTROY ROSTED DATER 11 March 1968

1/EAH/wjs T: April 1968

3T 43/073	SERVNO	RANK	MOS	PRIMARY DUTY
<u>NAME</u> Headquarters Co	DITTANO	LUMIT		
FUNDERBURK, RAY	045512	LtCol	1302/0302	BnCmdr
HANNAN, J. E.	049923	Major	1302/0402	BnExecO
BAISLEY, T. R.	080663	Capt	1302	S-4
FRANZWA, R. E.	083290	Capt	1302/0430/5715	S
HUFNAGEL, E. A.	079266	CWO	0130	S-1/Adj/Legal ConstPltCndr
IVEY, B. D.	076764	CWO	1360/0210/1320	HqCoCmdr/CommO
LEWIS, T. D.	093253	Capt	2502	Asst S-4
OCONNELL, P. J.	0100566	1stLt	3002	EngrEquipPltCmdr
PERKINS, W. N.	097607	1stLt WO	1310 1360	Asst S-3
SOWA, J. J.	099389 09264 1	Capt	1302	Asst S-3
SMITH, R. D.	092041	1stLt	1302	CivAffairs0
TURSE, E. J. WARDLAW, C. M.	0100102	1stLt	1302	S-2
WIRDIAW, Ce. He.	0100102	100-0		•
Service Co				
HUNTZINGER, R. A.	059050	Major	1302	ServCoCmdr
BARBER, J. S.	096092	1stLt	3010/3502	BnSup0
CARVER, R. E.	0935 75	1stLt	1320/0430	ExecO MaintPltCmdr
CROSS, C. F.	093588	1stLt	1320/1310	UtilPltCmdr
DICKERSON, C. R.	096541	1stLt WO	1 320 1310	AsstMaintPltCmdr
FELTY, D. W. Jr.	098649 01 01347	1stLt	3502	BnMTO
NORRIS, L. D.	0101541	10000		
"A"Company				
RIVERA, J. D.	092528	c_{apt}	1302	"A"CoCmdr
AOYAMA, K. M.	0103117	2ndLt	1301	PltCmdr
CRAM, A. B.	0103164	2ndLt	1301	PltCmdr ExecO
DOWNEY, J.	096544	1stLt	1302/0430	PitCmdr
KRUGER, L. W.	0102065	1stLt	1302	PltCmdr
TIMERMAN, J.H.	0103845	2ndLt	1301	
"B"Company	· ·			· ·
ESPOSITO, M. J.	093085	Capt	1302/1320	"B"CoCmdr
CLARK, R. D.	0103407	2ndLt	1 30,1	PltCmdr
HAGGERTY, J. J.	094412	1stLt	1302	Exec0
LONG, R. L.	0102094	1stLt	1302	PltCmdr
SAWYER, B. B.	0102263	1stLt	1302	PltCmdr
SOOK, R.	0102847	2ndIt	1301	PltCmdr
"C"Company				
BUCKELEW, J. D.	089393	Capt	1302	"C"CoCmdr
DENIKER, J. E.	0100995	1stLt		PltCmdr
MANGE, G. B.	0100458	1stLt		PltCmdr
MORRISON, A. E. J.		1stLt		PltCmdr FracO
REID, G. H.	095009	1stLt	1302	ExecO

÷

NAME TD''Com		SERVNO	RANK	MOS	×.	PRIMARY DUTY	
LOPEZ, ADAMS, HILLIAR KEPFORI		09326 1 0100356 094276 095518 0100393	Capt 1stLt 1stLt 1stLt 1stLt	•		"D"CoCmdr PltCmdr PltCmdr ExecO PltCmdr	
<u>1stBrid</u> ROCCO, MCRLAN, NICOL, PEASENH UNGERN,	<u>geCo</u>	093399 0103700 0101343 094979 0102352	Capt 2ndLt 1stLt 1stLt	1302 1301 3002/0430 1302		1stBridgeCoCmdr PltCmdr SupplyO ExecO PltCmdr ServPltCmdr	
BEATY, DEARBON JOHNSON PEASE, SELDEN,	ly DeLo	092742 0101605 0100988 0101180 0102199 0101671 0101525	1stLt 1stLt 1stLt		•	3rdBridgeCoCmdr PltCmdr PltCmdr ExccO PltCmdr PltCmdr SupplyO	and the second se
HARYASZ	N, P. E. 2, F. S. T. W.	715724 712088 723525	Lt Lt Lt	2105 4105		BnSurgeon BnChaplain DentalOff	

.